



Description: Guide to create “Smart Symbols” in GraphWorX64
OS Requirement: Windows 8 x64 (Professional or Enterprise Edition) /Windows 7 x64 (Professional or Enterprise Edition) /Windows Server 2012 x64 /Windows Server 2008 R2 x64 /Windows Vista x64 SP2 (Business, Ultimate, or Enterprise Edition) /Windows Server 2008 x64
General Requirement: General understanding GraphWorX64

Introduction

Smart Symbols are an enhanced version of object groups. They greatly simplify the configuration and save engineering time by allowing the configuration of properties of inner objects without a need to drill into the symbol.

- Smart Symbols are groupings of graphical objects. They are created from object groups using a wizard, which simplifies the binding of smart properties to properties of the descendant objects.
- Similarly, to object groups, Smart Symbols can be stored in the Symbol Library and reused later.
- Smart Symbols appear as a special kind of object in the object Explorer.
- Smart Properties appear in the Property Pane in a section called Smart Properties.
- Smart Properties of Smart Symbols can be added, edited, and removed at any time.

Creating a Simple Gauge

1. Open a new GraphWorX display by going to **Start → All Programs → ICONICS → GENESIS64 → GraphWorX64 → GraphWorX**
2. Create a circle using the “Ellipse” shape tool. Hold down the shift key to create a circle.




Figure 1 - Create a Circle

3. Inside the circle, create a polygon that looks like a needle (or just a vertical line for simple graphics).




Figure 2 - Create a polygon

4. Add a Process Point.




Figure 3 - Insert a Process Point

5. Select an OPC Tag for the Process Point. You can choose a simulated signal for this purpose.
6. Select the former created polygon (or vertical line) and choose “Rotation” from the “Dynamics” ribbon.



7. Change the Pivot point by dragging the red dot to the center of the circle you created at the beginning.




Figure 4 - Change the Pivot Point

8. Define the start angle and end angle, either by entering the values in the dynamics pane or by dragging the shadow object of the needle to the start and end location.




Figure 5 - Set Start and End Angle

Select the same OPC Tag you chose for the Process Point as Data Source from the dynamics pane. This is important, as we want the same value reflected in the rotation as well as displayed in the process point.




Figure 6 - Select Data Source

9. Select all objects (Circle, Polygon and Process Point) and group them using the group function on the Home tab of the ribbon.




Figure 7 - Group Selected Objects

The group has become one object now. While the group object is selected, go to the "Dynamics" tab of the ribbon and select "Convert Symbol".





Figure 8 - Converting a Symbol

The smart symbol wizard pops up. Check the "Expose data sources as Smart Properties" option to make the Data Source a smart property. You can leave the second option unchecked.



Picture 1 Smart Symbol Wizard

10. Click OK to get to the next dialog. Here define the name of the exposed data source. In our case we want to rename "localsimtriangleGauge0101000100" to something more readable like "DataSource". Click OK.




Figure 9 - Smart Properties

11. Congratulations! You have created a simple smart object. You can duplicate this object and change the data source by selecting a different OPC-Tag through the smart property "DataSource".




Figure 10 - Smart Properties DataSource

12. If you have your symbol library open, you can drag (CTRL-Drag) and drop your smart symbol to the library so that it is available to all your projects.

Adding a Smart Property

You can add smart properties to any smart symbol. In this section, we will detail how to expose the color property of the gauge needle created in the previous section.

1. Having your smart symbol selected right-click on it and select "Edit Group".
2. Select the polygon. In the properties pane select "Fill" and right-click on it to bring up a menu. Select "Add to smart properties".




Figure 11 - Expose Properties as Smart Properties

3. The Add Smart Property dialog comes up. Give this property a name; in the example we called it "NeedleColor". Click OK.




Figure 12 - Define Property Name

13. Browse to your Smart Symbol's Smart Properties and you will see the newly added color property. Don't forget to add this new Smart Symbol into your Library again. Whenever you use it, you can change its data source and the color of the needle by editing the appropriate smart property.




Figure 13 - Added Needle Color Property